曜凌光電股份有限公司
Raystar Optronics, Inc.
42881台中市大雅區科雅路25號5樓
5F, No. 25, Keya Road, Daya Dist., Taichung City 42881, Taiwan
T：+886-4-2565-0761 | F：+886-4-2565-0760
sales@raystar-optronics.com | www.raystar-optronics.com

Issue Date: July. 15th, 2021

Notification Subject: IC Vendor informed PCN driver IC SC7283-G4


- **Description:** The IC vendor informed changing Wafer Plant due to original IC Wafer Plant's capacity is fully occupied. We also modified the VDDI range and added a set of capacitors from VCC to ground to enhance the ESD ability.

- **Effected model:** RFE430W Series

- **Planning Changing Time:** As soon as the current stock running out.

Parts No.	Before Change: ICSC7283321XXXXXXX00	After Change: ICSC7283321XXXXXXX01
FPC Appearance (FPC has been modified with the circuit according to the supplier's recommendations)		
Module Appearance (Performance remained the same)		

曜凌光電股份有限公司
Raystar Optronics, Inc.
42881台中市大雅區科雅路25號5樓
5F, No. 25, Keya Road, Daya Dist., Taichung City 42881, Taiwan
T：+886-4-2565-0761 | F：+886-4-2565-0760
sales@raystar-optronics.com | www.raystar-optronics.com

Module Appearance (Performance remained the same)	
Module Appearance	

Raystar appreciated your support and we will continue do our best to provide our products to customers. If there have further questions, please feel free to contact with us at any time.

Best regards

Raystar Optronics; Inc